

404.371.2155 (o) 404.371.4556 (f) DeKalbCountyGa.gov

178 Sams St Decatur, GA 30030

Chief Executive Officer

### DEPARTMENT OF PLANNING & SUSTAINABILITY

Interim Director Michael Thurmond Cedric Hudson

Inspector Name: A. McDyess/E. Emmett/D. Pearson	Date: 4/4/2023		
Owner/Tenant/Contractor: Alan Williams	Phone: 770-354-3392		
Address of Subject Property: 561 Key Rd / 1350 Constitution	District/Zone: 15 081 08 001		
Permit No.: 1245564	NPDES Tracking No. N/A		
Site Visit Purpose:  - Follow-up site inspection after the Zoom appointment It has been confirmed that all the violations from the site visit on 3/28/2023 and the corrective maintenance recommendations made by the inspectors have been corrected and compliance has been obtained.	Compliance/Violation Determination: -BMPs compliance obtained -Silt Fence in the GA Power Easement Area that the protesters damaged/destroyed has been corrected No sediment escape or environmental impacts observedRepairs to all the silt fence and tree protection has been made, the site is in compliance and is environmentally up to DeKalb County Ordinance.		
Notice of violations Issued? No, construction violations were observed.	Stop Work Order issued?		
Follow up action: TBD	Re-inspection date: TBD		
Violations code reference: None			
Referred to another department/division: No			

#### **General Observations**

Storm water violation	NO	Rain Fall Incident?	NO
Construction site violation	NO	Discharge event?	NO
BMP's Install Properly?	YES	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	NO
During Storm event	N/A	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	N/A
Post Storm Event?	YES	Are all slopes and disturbed areas not actively being worked properly stabilized?	N/A
Stream buffer violations?	NO	Are discharge points and receiving waters free of sediment deposits?	N/A

# **Report Certification**

Position/Title:	Name:	Signature	Date
Site Inspector	Deidra Pearson	D. Down	4/5/2023

# **Inspection Photos:**

## **COMPLIANCE STATUS:**





Previously Destroyed Perimeter Silt Fence at Power Easement Area





ENTRANCE on KEY ROAD (33.69685841N 84.33796873W)





Silt fence repaired where fallen tree damage took place; Hay bales and an extra row of silt fence was added for additional stabilization